REFRIGERANT, FILTER DRIERS, ACCESS VALVES





REFRIGERATION PARTS & ACCESSORIES

REFRIGERANT FILTER DRIERS
LIQUID LINE - Sweat Connections

MODEL		
BF083S 3/8" Liq. Line Drier	Each	1
C305S 5/8" Liq. Line Drier	Each	1
C164S 3/8" Liq. Line Drier	Each	1
HPC-163S 3/8 Liq.Line Heat Pump Drier	Each	1
HPC-164S 1/2 Liq.Line Heat Pump Drier	Each	1

FILTER DRIERS
SUCTION LINE - Sweat Connection

MODEL	CONN. I.D	FILTER AREA	FLOW IN TONS @ 40 Deg. F
C165S-T-HH	5/8"	33	2.0
C305S -T-HH	5/8"	30	1.5
SLD136SV-HH	3/4"		7.00
SLD137SV-HH	7/8"		7.00
SLD138SV-HH	1-1/8"		7.00

C-165-S 5/8" Suction Drier	Each	1
C-305-S 5/8" Suction Drier	Each	1
SLD136SV-HH 3/4" Suction Drier	Each	1
SLD137SV-HH 7/8" Suction Drier	Each	1
SLD138SV-HH 1-1/8" Suction Drier	Each	1
S-286T 3/4 Suction Heat Pump Drier	Each	1

DESCRIPTION	Unit	Qty.	Price

GEM HERMETIC SERVICE VALVES
Access Schrader Valves - Screw In or Sweat In
Includes Schrader Core and Cap

HS8403 - 3/16" Tube Tap Valve	Each	1
	Pkg.	6

GEM HERMETIC COPPER TO COPPER SADDLE VALVES
Sweat Saddle Valve - Includes Schrader Core and Cap

To Install: Pull copper body down over tubing and pinch with fingers or pliers and solder valve body to line. Place teflon seal over pin and core and drop into valve body. Screw 1/4" cap down, which drives pin and pierces tubing, and locks pin in valve body. Remove cap to charge unit.

HS5514 Herm.Saddle Valve - 1/4	Each	1
HS5538 Herm.Saddle Valve - 3/8	Each	1
HS5512 Herm.Saddle Valve - 1/2	Each	1

GEM HERMETIC SERVICE VALVE ACCESSORIES

HV1515 Replacement Valve Core	Each	1
HV2250 Brass Cap With O-Ring	Each	1